

### Pipe Conversion Chart - Escondido Metal Supply

PIPE SIZE	O.D. in INCHES	5S	5	10S	10	20	30	40S	40	60	80S	80	100	120	140	160	DBL XXH
1/8	.405		.035	.049	.049			.068	.068		.095	.095					
1/4	.540		.049	.065	.065			.088	.088		.119	.119					
3/8	.675		.049	.065	.065			.091	.091		.126	.126					
1/2	.840	.065	.065	.083	.083			.109	.109		.147	.147				.187	.294
3/4	1.050	.065	.065	.083	.083			.113	.113		.154	.154				.218	.308
1	1.315	.065	.065	.109	.109			.133	.133		.179	.179				.250	.358
1-1/4	1.660	.065	.065	.109	.109			.140	.140		.191	.191				.250	.382
1-1/2	1.900	.065	.065	.109	.109			.145	.145		.200	.200				.281	.400
2	2.375	.065	.065	.109	.109			.154	.154		.218	.218				.344	.436
2-1/2	2.875	.083	.083	.120	.120			.203	.203		.276	.276				.375	.552
3	3.500	.083	.083	.120	.120			.216	.216		.300	.300				.438	.600
3-1/2	4.000	.083	.083	.120	.120			.226	.226		.318	.318					.636
4	4.500	.083	.083	.120	.120			.237	.237		.337	.337		.438		.531	.674
4-1/2	5.000							.247			.355						
5	5.563	.109	.109	.134	.134			.258	.258		.375	.375		.500		.625	.750
6	6.625	.109	.109	.134	.134			.280	.280		.432	.432		.562		.719	.864
7	7.625							.301			.500						.875
8	8.625	.109	.109	.148	.148	.250	.277	.322	.322	.406	.500	.500	.594	.719	.812	.906	.875
9	9.625							.342			.500						
10	10.75	.134	.134	.165	.165	.250	.307	.365	.365	.500	.500	.594	.719	.844	1.000	1.125	1.000
11	11.75							.375			.500						
12	12.75	.156	.165	.180	.180	.250	.330	.375	.406	.562	.500	.688	.844	1.000	1.125	1.312	1.000
14	14.00	.156		.188	.188	.312	.375	.375	.438	.594	.500	.750	.938	1.09	1.250	1.406	
16	16.00	.165		.188	.188	.312	.375	.375	.500	.656	.500	.844	1.031	1.22	1.438	1.594	
18	18.00	.165		.188	.188	.312	.438	.375	.562	.750	.500	.938	1.156	1.38	1.562	1.781	
20	20.00	.188		.218	.218	.375	.500	.375	.594	.812	.500	1.031	1.281	1.500	1.750	1.969	
24	24.00	.218		.250	.250	.375	.562	.375	.688	.969	.500	1.219	1.531	1.812	2.062	2.344	